



APRIL 11, 2001

Mr. Gary E. Walsh Executive Director The Public Service Commission of South Carolina P. O. Drawer 11649 Columbia, S. C. 29211



Dear Mr. Walsh:

IN RE: Application of Dowd Water System for of an Increase in Water Rates for Stephenson's Lake DOCKET NO. 2001-75-W

Attached hereto is my application for a rate increase for Stephenson's Lake subdivision which I own and manage. I would appreciate it if you could render a decision as soon as possible since I am losing money on its operations.

Very sincerely yours,

Sue Dowd Dowd Water System 77 Dowd Road Prosperity, SC 29127

APPLICATION OF STEPHENSON'S LAKE DOCKET NUMBER 2001-75-W

INFORMATION TO BE FILED WITH THE COMMISSION FOR AN INCREASE IN WATER AND OR SEWER RATES AND CHARGES

1. Stephenson's Lake operated at a loss for the twelve months ended December 31, 2000 and a negative operating margin of (12.67%). On April 1, 2001, an independent contractor began testing the system at an additional costs of \$6,618 per year. Because of the losses and the lack of available funds, the owner does not receive a salary for managing the system.

After pro forma and accounting adjustments, the system is operating at a loss of \$4,609 and an operating margin of <u>negative</u> 102.42%. Relief is needed quickly in order to maintain proper service to the customers.

- 2. See Attachment 1 and 1-A
- 3. Proposed rate schedule:

Proposed monthly rate: \$51.00 per month for unlimited usage

Disconnect Fee: \$90.00 (\$75.00 Contract Cost plus mailings and travel by owner, \$15.00) Reconnect Fee: \$90.00 (\$75.00 Contract Cost plus mailings and travel by owner, \$15.00)

- 4. The test year to be used is the twelve months ended December 31, 2000. See Attachment 1 and 1-A Attached.
- 5. Pro Forma Income and Expense Statement. See Attachment 1 and 1-A.
- 6. During the year 2000, this company was an individual proprietorship and no Balance Sheet was maintained. The company request a waiver of this item.
- 7. There is no depreciable property since the assets are fully depreciated.
- 8. The system is maximized out. No additional customers can be added.
- 9. The customers would receive unlimited amounts of water for the proposed rates of \$51.00 per month. After the proposed rates, the Operating Margin is 32.39%. Since the owner does not receive any compensation from the company, but is having to put money into it, the cost per month is justifiable.
- 10. Performance Bond. Separate Item. Hand delivered along with item 11 below.
- 11. Service map. Provided by separate cover because of bulkiness along with item 10 above.
- 12. Total plant investment. All plant has been fully depreciated. The replacement cost, though, has been appraised at \$46,320.
- 13. Most recent letter from DHEC. See Attachment 2.
- 14. Customer Bill Form. See Attachment 3
- 15. Because of losses incurred by this utility, I request that my application be heard and a decision be made by the Commission as soon as practical.

STEPHENSON'S LAKE

STEPHENSON'S LAKE OPERATING MARGINS FOR THE TEST YEAR ENDING DECEMBER 31, 2000

		PROFORMA AND		EFFECT OF	AFTER
	PER	ACCOUNTING AD	J. AFTER	PROPOSED ADJ	PROPOSED
	BOOKS	ADJUSTMENTS NO	D. ADJUSTMENTS	INCREASE NO.	INCREASE
	\$	\$	\$	\$	\$
OPERATING REVENUES:	4,500	0	4,500	10,800 (5)	15,300
					-
OPERATING EXPENSES:					
Electricity	1,157	0	1,157	0	1,157
Testing Fees	500	(500) (1)	0	0	0
Operator	1,800	4,818 (1)	6,618	0	6,618
Chemicals	186	(186) (1)	0	0	0
Office Supplies (1)	220	0	220	0	220
<u>.</u>					
Repairs	1,047	0	1,047	0	1,047
Danais Dana		(70) (0)	_		
Repair Door	50	(50) (2)	0	0	0
Assessment Taxes	440	(07) (0)		54 (0)	
Assessment Taxes	110	(87) (3)	23	54 (6)	77
Property Taxes	0	•	•	•	•
Floperty Taxes	U	0	0	0	0
Management Fees	0	0	0	0	0
Management rees	U	U	U	U	U
Rate Case Expense	0	44 (4)	44	0	44
Nate Case Expense	J	44 (4)	44	U	44
Income Taxes	0	0	0	1,181 (7)	1,181
	<u>~</u>		<u> </u>	1,101 (7)	1,101
TOTAL OPERATING EXPENSE	5,070	4,039	9,109	1,235	10,344
			0,100	1,200	10,044
TOTAL OPERATING INCOME	(570)	(4,039)	(4,609)	9,565	4,956
= = = =			χ.,,σσσγ		.,,,,,,,
OPERATING MARGINS:	(12.67%)		(102.42%)		32.39%
-					

AHACHMENT #1-A SPEPHENSON'S LAKE

DOWD WATER SYSTEM (STEPHENSON'S LAKE) DOCKET NO 2001-75-W

EXPLANATION OF ACCOUNTING AND PRO FORMA ADJUSTMENT

ADJUSTMENT NUMBER 1: Testing Fees, (\$500); Operator Fees, \$4,818; and Chemical Costs, (\$186). Effective April 1, 2001, a private contractor assumed the responsibility of all testing at Stephenson's Lake and Emerald Shores at \$1,103 per month (\$13,236 per annum). One-half of this cost, or \$6,618, is charged to Stephenson's Lake.

<u>ADJUSTMENT NUMBER 2</u>: Repair Door,(\$50). Repairs to a door is eliminated as an extraordinary and nonrecurring costs.

<u>ADJUSTMENT NUMBER 3:</u> Assessment Taxes (\$87). The assessment tax by the Public Service Commission of South Carolina is annualized at .005 times \$4,500, thus, reducing the adjusted amount to \$23.

<u>ADJUSTMENT NUMBER 4:</u> Rate Case Expense, \$44. The cost by the Accountant is \$400 for three dockets. One-third of this amount, \$133, is amortized over a three-year period.

ADJUSTMENT NUMBER 5: Effect of the Proposed Increase, \$10,800. The proposed increase is \$36 per month for twenty-five customers (\$36 X 25 customers X 12 months equals \$10,800).

<u>ADJUSTMENT NUMBER 6:</u> Assessment Tax, \$54. The gross receipts tax is computed at .005 times the proposed increase of \$10,800.

<u>ADJUSTMENT NUMBER 7</u>. Income taxes, \$1,181. On proposed Revenues of \$15,300 and proposed Expenses of \$9,163, taxable income is \$6,137. The taxable rate of 19.25% was applied for Income Taxes of \$1,181.



FACHMENT #2 EPHENSON'S LAKE

CENTRAL MIDLANDS EQC DISTRICT PO Box 156, Building #5 State Park, SC 29147 (803) 896-0620 Fax (803) 896-0617

April 4, 2001

Sue Dowd 77 Dowd Road Prosperity, SC 29127

RE:

Sanitary Survey of Stephenson's Lake, Emerald Shores, and Isle of Pines

Water System Number 3250018, 3250088, 3250062

Lexington County

Dear Mrs. Dowd:

On March 22, 2001, a follow-up sanitary survey of the above referenced water systems was conducted by South Carolina Department of Health and Environmental Control (the Department) personnel. Present at the time of the survey was Sue Dowd, the owner of the system. The intent of a survey is to evaluate a public water system's ability to provide a continuous supply of safe drinking water to its customers following the guidelines established by the State Primary Drinking Water Regulations, (R.61-51).

The enclosed sanitary survey report consists of a list of the deficiencies that were noted during the survey, along with any general comments or recommendations concerning the water system and its operation.

The following deficiencies were noted and recommendations are made: Bold typeface indicates any changes from the original Survey of April 10, 2000.

Stephenson's Lake

- Item #2: Protection from contamination- Well two (2) was missing a screened air vent. The vent must be replaced in order to prevent potential contamination from entering the well. The vent can be a goose neck type with twenty-four (24) mesh screen over the opening, or manufactured slotted pipe with effective opening of .024 inches or smaller (R.61-58.2 (B), page 15).
- Item #3: Security- The locks on both wells five (5) and six (6) need to be fixed. 2.
- Item #10: Chemical feed rooms- When the chlorine drum is replaced, it needs to be graduated. Also, the operator must use a graduated container to fill the chemical drums, so that a precise measurement of the amount of chemical added can be recorded in the log.
- Item #17: Valve/hydrant maintenance- The valves must be exercised at least once a year. When 4. this is done it must be documented and, kept in your files with the other records.
- Item #18: Flushing Program- There was no written flushing program on hand during the survey. 5. Enclosed is a sample plan, which can help you to develop your own program.

ATTACHMENT FALLE

STEPHENSONS LAKE

PAGE 2

by a perimeter fence. Preferably,
d-wire capping. This will decrease

btage (R.61-58.7 C (18), page

s rusting and needs to be repainted.

tting a storage tank, (R.61-58.7 E

repainting of existing storage

noperable.

ed operator with at least a D

d license number of the operator

- 6. Item #25: Storage security- Both storage tanks must be secured by a perimeter fence. Preferably, the fence should be a minimum of six (6) feet tall and should have barbed-wire capping. This will decrease the probability of contamination due to vandalism, tampering and/or sabotage (R.61-58.7 C (18), page 222).
- 7. Item #27: Maintenance- The storage tank at the chemical room is rusting and needs to be repainted. The Department must be notified, in writing, ten (10) days prior to repainting a storage tank, (R.61-58.7 E (14), page 226). Included with this report is a guidance document on the repainting of existing storage tanks. Also, the pressure gauge on the storage tank at well two (2) is inoperable.
- 8. Item #28:Certified operator- This system must have a certified operator with at least a D grade license. Please provide to this office immediately, the name and license number of the operator in charge of this system. Per our phone conversation of March 30, 2001 at 9:30 AM, E.A. Services will provide the certified operator starting the week of April 1-7, 2001. Per a phone conversation between Mrs. Sue Dowd, and Mr. Larry Boland, of the Department, operators will be checking the system three (3) times a week. Please note that a certified operator <u>must make daily visits</u> to the system.
- 9. Item #30: Monitoring/reports/record keeping- Please mail the Department copies of your bacteriological monitoring reports, sample siting plan, and operator logs for the past 12 months. There were no operator's logs on hand in the chemical rooms.
- 10. Item #35: Procedures Manual- Each system must have a procedures manual which would include the following:
 - A. Detailed instructions on starting and stopping any treatment plant
 - B. Preventative maintenance procedures and schedules for equipment
 - C. Water quality monitoring records
 - D. Reporting and public notification requirements
 - E. Sampling and analytical procedures for monitoring water quality
 - F. Sample siting plan
 - G. Valve and hydrant maintenance procedures
 - H. Distribution system flushing program
 - I. Disinfection requirements for the repair of wells, tanks, and water lines
 - J. Cross-connection control program
 - K. Leak detection and repair program
 - L. Safety procedures

Enclosed is a sample procedures manual which you can use to develop your own.

- 11. Item #37: Emergency Plan- All systems must have an emergency plan which contains the following information
 - A. The telephone number of the Department's district office, the Department's Bureau of Water office and the Department's twenty-four hour telephone number.
 - B. The names and numbers of current chemical suppliers
 - C. The names and numbers of the electric, natural gas, telephone and cable companies
 - D. The names and numbers of the potential sources of spare parts, pipe sections and pipe repair parts.
 - E. The names and telephone numbers of contractors to call for making any repairs

STEPHENSONS LAKE PAGE 3

beyond the capability of the system personnel.

- F. The names and numbers of well drillers
- G. Arrangements for obtaining emergency power.
- H. Arrangements for obtaining potable water
- I. An up-to-date distribution map showing line sizes, the location of larger valves, fire hydrants, blow-offs, and pumping, storage, and treatment facilities
- J. Procedures for notifying the public and media including a sample Boil Water Notice and a sample Boil Water Advisory.
- K. Emergency disinfection procedures for wells, water lines and storage tanks.

Enclosed is a sample emergency plan which will be helpful in developing your own plan.

Emerald Shores

- Item #2: Protection from contamination- The seal at well two (2) must be caulked to avoid potential contamination from entering the well. Also, the cement pad at well one (1) has a small crack that must be patched.
- Item #3: Security- the well house at well 2 must have a lock. 2.
- Items #7-11: Water treatment- Chlorination was added sometime after the 1996 survey. This was done with out proper approval from the Department. A construction permit must be obtained prior to placing any treatment program on the system. To obtain a permit for the chlorine feed system, plans and specifications from a professional engineer licensed in the state of South Carolina must be submitted to Mr. Chris Childs at 2600 Bull St., Columbia, SC 29201-1708. Please have these items submitted by May 4, 2001.
- Item #25: Storage security- see #6 of Stephenson's Lake 4.
- Item #27: Maintenance- see #7 of Stephenson's Lake 5.
- Item #28: Certified operator- see #8 of Stephenson's Lake 6.
- Item #30: Monitoring/reports/record keeping- see #9 of Stephenson's Lake 7.
- Item #35: Procedures manual- see #10 of Stephenson's Lake 8.
- Item #37: Emergency plan- see #11 of Stephenson's Lake 9.

In November of 2000, work was performed on both wells in Emerald Shores. Subsequently, one of the wells has been offline. As of March 30, 2001, both wells are back online and operating properly.

Isle of Pines

- Item #2: Protection from contamination- the wiring at the well must be put in conduit, and the well must have a cement pad which is six feet by six feet and 4 inches thick with the well centered. This will protect the well from potential contamination from surface water.
- Item #20: System map- There was no system map on hand during the inspection. Each system must have a map which includes where the well, tanks, and water lines are located. This map will aid in the

ALCHMENT # 2 SHEPHENSONS LAKE PAGE 4

operation of the system and in response to emergency situations.

3. Item #30: Monitoring/reports/record keeping- Please mail the Department copies of your bacteriological monitoring reports for the past 12 months and the sample siting plan.

All items were unchanged from the previous survey. Each item was reviewed by myself and Mrs. Dowd and I have enclosed information to help explain several of the deficiencies. The overall ratings of the above-mentioned systems are 'Unsatisfactory' due to the deficiencies from the previous survey not being corrected. Also, it is imperative that Stevenson's Lake and Emerald shores are visited daily by a certified operator. Thank you for your time and assistance. If you have any questions, please contact me at 896-0620.

Sincerely, S. Mi S. h. Cullneath

S. Michele Culbreath

Central Midlands EQC District

CC: Doug Kinard, DHEC Drinking Water Compliance

Susan Alder, DHEC Drinking Water Sue Ferguson, Palmetto Health District Lexington County Health Department

S. C. Department of Health and Environmental Control - Bureau of Water

PUBLIC WATER SYSTEM SANITARY SURVEY REPORT GROUNDWATER SYSTEMS

System	Namp	!	STEPHENSON'S	LAKE
コスンドに母	(3 CC #15)	1	CARTIFICATION OF	

System Number: J250018

LAST SURVEY: 04/10/2000

Affachment #2 Stephenson's LAKE Page 5

SURVEY Date: 3 12101

A Protection from contam I V S A Security	23. Capacity	8 Ø B Ø
4. Wellhead piping S	24. Sanitary protection S	D.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
5. Pumps.,,.,	25) Security	
6.Flow meter	26. Bypass/drain/tap 3	C. Field Tests
HATER TREATMENT:	27. Maintenance	Chloring
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Dii
8. Equipment 0 & M S	(28) Certified operator	981
9. Chemical storage 3	29. Testing equipment 5	Other
18. Chemical feed roomsLU	Monitor/Rpt/Record keep. U	
*** ******* ******* ********	ENERAL O & N:	O. Samples Taken
ISTRIBUTION:	31. Plant Security N	Bacteriological
12. Water Quality	32, Facility maintenance S	Inorganic Organic
13. Operation & Control S	33. Supplies/spare parts S	Radiological
14. Adequate pressure §	34. Waste disposal M	Other
15. Fire flow N	85) Procedures manual	E. Type Inspection ROUTINE
10. 11 221111111111111111111111111111111	MERGENCY OPERATION:	F. Are All Services Metered? N
17. Valve/hydrant maintenance.LU	36. Stand-by power N	Percent Metered
18. Flushing program	(57) Emergency plan	6. Is System Presently Under Order.
3.17	fisc. Old Survey	H. If Yes, is System Complying W/ Order.
20. System map 8	38. CCR	I. Follow-up Scheduled?
		Date Scheduled / /
		J. Overall Rating
		Operator/Owner Present? Y
110 missing of Jour	COMMENTS	Deperator/Owner Present? Y Ls (101) drum must be goodvated as tank must be secured in fau rator must visit daily ting plan (35+36) Must develop Procedures manual and Emergency plan
Mal & Missing all regist	3) Well 306 Must have loc	ES (101)
THEORY MUST have do cump	ntation of these items	(25) tank Must be secured in the
10	1 1 60 Cate and Oper	cator Must visit daily
Tranks must be min	ited (29 CEITHIR OPE	1 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2
) lanks may be pring	. I so He and sample S!	ting plan (35 +36) Must develop
A Nict have horterial	paical results are saint) Trac Manual and
of 19059 Thire series		Procedures might
	_	Procedures manual and Emergency plan
JAM I. C. C. Conth	<i></i>	<i>/ /</i>
M. S.	an and the last that the last that the sept and the last size and the same and the last size and the l	oper man wall fast only the last definition and 1991, get have the first out to the first that the last to the first that the last to the first that the first the first the first the first the last to the last
OHEC Representative		

Dowd Water System 77 Dowd Road Prosperity, SC 29127 AH H M ENT # 3
Stephenson's Lake

803-345-2285

Mr. P. O. Box Chapin, SC 29036

Sue Dowd

2000		
January		and the second seco
February	relative to the second of the	and the state of t
March		ATTIVITY OF THE PROPERTY OF TH
April		
May		
June		NAME OF THE PERSON OF THE PERS
July		egwide allas passeres es i till albert fe
August	The second secon	Color de la color
September		
DHEC Fees	,	
Past Due		
Galley D. Serv. (September 1997) (September 1997) (September 1997) September D. Serv. (September 1997) September D. Serv. (September 1997) (September 1997) September D. Serv. (September 1997		
Total Amount Due	Date Due	
Thank you.		